

BUTTERFIELD PARK MASTER PLAN



Failing Structure for Lighting Controls



Tennis Courts in generally good condition



Table seating near Recreation Building



Ponded water and drainage concern behind Elmhurst College Baseball Field



Failing foundation for drinking fountain



Unscreened garbage dumpsters



Failing retaining wall and drainage problem at small drain inlet near restrooms



Cracking concrete retaining wall at parking lot above restrooms



Basketball hoop in parking lot



Drainage route over sidewalk



Ponded water at trail connection



Ponded water at bleachers



Ponded water on asphalt path




Ponded water behind baseball field



Field drainage into tennis courts



Field stone washing off baseball field



Playground



Ponded water near picnic structure



Butterfield Road near sidewalk



Open picnic rental area

EXISTING CONDITIONS

